

DMR Copy of Record

Permit

Permit #:MA0004936

Major:Yes

Permitted Feature:002
External Outfall

Permittee:PATRIOT BEVERAGES, LLC

Permittee Address:C/O CPF, INC. 25 COPELAND DR.
AYER, MA 01432

Discharge:002-A
STORMWATER/DETENTION POND

Facility:PATRIOT BEVERAGES LLC

Facility Location:20 HAVARD ROAD
LITTLETON, MA 01460

Report Dates & Status

Monitoring Period:From 04/01/19 to 04/30/19

DMR Due Date:05/15/19

Status:NetDMR Validated

Considerations for Form Completion

SAMPLE MONITOR LOCATION AT VAULT MARKED S/N 002 PRIOR TO MIXING WITH ANY OTHER DISCHARGE OR REEDY MEADOWBROOK. REPORT MAXIMUM, MINIMUM + TOTAL FLOW RATES FOR EACH STORM EVENT. *

Principal Executive Officer

First Name:JAMES

Last Name:DRAPEAU

Title:CHIEF WASTEWATER OPERATOR

Telephone:978-339-5905

No Data Indicator (NODI)

Form NODI:--

Parameter		Monitoring Location	Season #	Param. NODI		Quantity or Loading					Quality or Concentration						# of Ex.	Frequency of Analysis	Sample Type	
Code	Name					Qualifier 1	Value 1	Qualifier 2	Value 2	Units	Qualifier 1	Value 1	Qualifier 2	Value 2	Qualifier 3	Value 3	Units			
X00530	Solids, total suspended	1 - Effluent Gross	0	--	Sample										=	212.7	19 - mg/L	1	01/30 - Monthly	GR - GRAB
					Permit Req.										<=	100 DAILY MX	19 - mg/L		01/30 - Monthly	GR - GRAB
					Value NODI															
00665	Phosphorus, total [as P]	1 - Effluent Gross	0	--	Sample										=	1.2	19 - mg/L	0	01/30 - Monthly	GR - GRAB
					Permit Req.											Req Mon DAILY MX	19 - mg/L		01/30 - Monthly	GR - GRAB
					Value NODI															
50050	Flow, in conduit or thru treatment plant	1 - Effluent Gross	0	--	Sample			=	0.677	03 - MGD								0	01/30 - Monthly	GR - GRAB
					Permit Req.				Req Mon DAILY MX	03 - MGD									01/30 - Monthly	GR - GRAB
					Value NODI															

Submission Note

If a parameter row does not contain any values for the Sample nor Effluent Trading, then none of the following fields will be submitted for that row: Units, Number of Excursions, Frequency of Analysis, and Sample Type.

Edit Check Errors

Parameter		Monitoring Location	Field	Type	Description	Acknowledge
Code	Name					
00530	Solids, total suspended	1 - Effluent Gross	Quality or Concentration Sample Value 3	Soft	The provided sample value is outside the permit limit. (Error Code: 1)	Yes

Comments

Due to snow melt off, rains and possible beaver intrusion, the Reedy Meadow Brook water level is high and backing up the flow from the storm water basin. This has caused high and incorrect flow readings

Attachments

Name	Type	Size
SignedAPR2019SWDMRcvrltr.pdf	pdf	470167
STORMWATERDISCHARGE-APR2019.xls	xls	26624

Report Last Saved By

PATRIOT BEVERAGES, LLC

User:jdrapeau@cpf-nehf.com

Name:James Drapeau

E-Mail:jdrapeau@cpf-nehf.com

Date/Time:2019-05-09 07:00 (Time Zone: -04:00)

Report Last Signed By

User:jdrapeau@cpf-nehf.com

Name:James Drapeau

E-Mail:jdrapeau@cpf-nehf.com

Date/Time:2019-05-09 07:36 (Time Zone: -04:00)